



[www.milbankmfg.com](http://www.milbankmfg.com)


## FIELD CHANGE NOTICE

### Gang Socket Redesign

July 2009

Milbank recently updated the design of our gang sockets to aid in the ease of assembly at our factory. We also took this opportunity to increase the spacing between the bus bars, allowing us to eliminate most of the black sleeving that we previously supplied. The only piece of sleeving that is required is located on the upper bus under the overhead entrance KO. This piece of sleeve will prevent the bare neutral conductor from contacting the live bus. Refer to the picture below as an illustration of the new design.

The increased spacing and removal of the black sleeving has been fully tested and is UL listed. The list of affected model numbers are; U1232-U1236, U1252-U1256, U1282-U1286, U3522-U3526 & U3763-U3765.



KANSAS CITY, MO • KOKOMO, IN • EL DORADO, AR • CONCORDIA, MO

P.O. Box 419028 • Kansas City, MO 64141-6028  
Local 816-483-5314 • Fax 816-483-6357 • Toll Free 877-483-5314