

IMPORTANT SAFETY NOTICE

Milbank Manufacturing Company recently became aware of a potential safety problem with some of our 200 Amp, 4 terminal, ringless underground meter sockets manufactured between May 1, 2009 and August 31, 2009.



Milbank Catalog Numbers
Sold through Electrical Distributors and
Local Hardware Stores

U9090-O
UPC 7-84572-14236

R9090-O (1033379)
UPC 7-84572-48084

Milbank has discovered that the units may have been made with an incorrect bridge. The incorrect bridge could cause a short circuit between phase bus and ground, posing a burn, and electrocution hazard. (The bridge supports the block assembly).

Please contact Mike Biggar, Milbank Manufacturing Company at 1-888-537-0881 ext 292 regarding replacement and repair information.

(Additional information can also be found at www.milbankmfg.com)